



NON-COMPLIANT AND KNOWN-COMPROMISED PIN ENTRY DEVICES

WorldPay strives to keep you informed about important compliance mandates and regulations affecting your business.

Current Card Association mandates require that all merchant acquirers and acquiring processors begin retirement of PIN Pad and terminal devices that are not compliant with PCI-PED security standards or that are on Visa's known-compromised device list.

Non-compliant devices must be removed from service no later than July 1, 2010, and known-compromised devices should be removed from service as soon as possible.

NON-PED-COMPLIANT DEVICES:

- Have not been evaluated on security standards by a third-party compliance organization
- Typically only support the less secure SDES and do not support the more robust TDES encryption

KNOWN-COMPROMISED DEVICES:

- Appear on Visa's known-compromised list
- Have been compromised at a merchant location
- Can subject merchants to a risk of fines up to \$500,000 per incident from Visa®, MasterCard® or other Card Associations if cardholder information is compromised in any way

WorldPay is urging retailers to consider replacing these devices quickly to avoid the risk of being non-compliant. Please see the lists of known-compromised and non-compliant devices along with possible replacement devices:

KNOWN-COMPROMISED DEVICES	POSSIBLE REPLACEMENT DEVICES
Hypercom S8 Pin Pad	Hypercom S9 PCI-PED
VeriFone Everest Pin Pad	VeriFone Mx830 or Vx850
VeriFone PIN Pad 101	VeriFone 1000SE PCI-PED
VeriFone PIN Pad 102	VeriFone SC 5000 PCI-PED
VeriFone PIN Pad 2000	

NON-COMPLIANT DEVICES	POSSIBLE REPLACEMENT DEVICES
Hypercom ICE 5500	VeriFone Vx510LE (3730LE) or Hypercom T4220
Ingenico eN-Crypt 100 PIN Pad	VeriFone PP 1000SE PCI-PED
IVI Sentinel PIN Pad	
Lipman Nurit 2085 Terminal	Add the external PIN Pad VeriFone PP 1000SE PCI-PED
Lipman Nurit 2085+ Terminal	
Lipman Nurit 3000 Terminal	VeriFone Vx510LE (3730LE)
Lipman Nurit 3010 Terminal	
NCR 5945 PIN Pad	VeriFone Mx830 or Vx850
NCR 5991 PIN Pad	
NCR 5992 PIN Pad	
Thales Talento T-IPP Terminal	VeriFone Vx510LE (3730LE)
Thales Talento T-IPPS Terminal	
Thales T-Pad PIN Pad	
VeriFone Omni 3210 Terminal	
VeriFone Omni 470 Terminal	VeriFone Mx830 or Vx850
VeriFone Omni 490	
VeriFone PIN Pad 1000	VeriFone PP 1000SE PCI-PED
VeriFone PIN Pad 1000SE (160 Firmware)	
VeriFone PIN Pad 1000SE G-Site (160 Firmware)	There is no PCI-PED-compliant device for G-Site Fuelman.
VeriFone SC5000 PIN Pad (Pulsar and Stardust model)	VeriFone SC5000 PCI-PED

To learn more or to order your PCI-PED replacement device, contact your WorldPay representative today at 866.232.8691 or visit: www.WorldPay.us.